



# KatRuud Positieve Voeding



Max 15 Vac  
Van  
Trafo

# KatRuud Positieve Voeding DIY



D1 t/m D6 = 1N400X

C3, C4 = 100n

C1 = 470u/35V (minimum)

C2 = 220u/35V (25V)

IC1 = 7812

F1 = Fuse holder + Fuse 500mA (1A max)

X1, X2 = 2 pole print connector

Pos PSU PCB